Program of the ARW'17 Workshop

Sunday 15 October	Time	Monday 16 October	Tuesday 17 October	Wednesday 18 October	Thursday 19 October	Friday 20 October	Saturday 21 October
	8:45	Workshop Registration 8:45-9:15		Leave Versailles 7:45 to Synchrotron SOLEIL (bus)			Optional Visit (bus): ORSAY Protontherapy Center (Institut CURIE) 8:45-12:00 Possible leave from ORSAY to Paris Return by bus to VERSAILLES at 12:00
	9:00	ARW Welcome Speakers: A. Nadji / L. Nadolski/ R. Giachino 01 Introduction to Reliability Scope, Goals, History of ARW Speakers: R. Giachino	05. Infrastructure Cryo, Electrical, Cooling Chair: P. Sampson	09. Maintenance for High Reliability Chair: D. Johnson	12. Medical Chair: S. Meyroneinc	16. High Intensity Reliability Chair: L. Conradie	
	10:30	Break	Break	Break	Break		
	11:00	02. Availability Tracking and Metrics Chair: R. Giachino	06. Accelerator Systems PS, RF, IonSource, Vacuum, etc Chair: V. Toma	10. Invited Speakers and round-table with participants Chair: K. Baggett and A. Nadji	13. Insuring Long Term Reliability Chair: D. Preddy	Poster and Picture Award Announcement Workshop Highlights Summary / Closing remarks Closing remarks LOC IOC Announcement of Next Workshop	
	12:30	Lunch	Lunch	Lunch	Lunch	End of Workshop	
	14:00	03. Reliability Before Design Chair: B. Todd	07. Accelerator Control Hardware, Software, Interlocks, etc. Chair: D. Newhart	Visit of Synchrotron SOLEIL	14. Parallel Discussions Training/Teaching Use Case	Optional Visit (15:00) Palace of Versailles	
	15:30	Break	Break	Break	Break		
	16:00	04. Plenary Discussion Chair: A. Nordt and D. Newhart	08 Failure Investigation Diagnostic, Post modum Root Cause, fault analysis Chair: K. Baggett	11. Poster Session Chair: E. Takada	15. Strategy for Continuous Reliable Operations Chair: L. Nadolski		
18h-20h Welcome Reception and Registration	17:30	Meeting Sponsors IOC Meeting		Return to Versailles (bus)	Meeting Sponsors IOC Meeting		
	18:30						
			Gala 20h-23h		IOC Dinner		