

Preliminary Program of the ARW'17 Workshop

Sunday 10 / 15	Time	Monday 10 / 16	Tuesday 10 / 17	Wednesday 10 / 18	Thursday 10 / 19	Friday 10 / 20	Saturday 10 / 21
	8:30	Workshop Registration		Leave Versailles to Synchrotron-SOLEIL (bus)			
	9:00	ARW Welcome Speakers: A. Nadji / L. Nadolski 01 Introduction to Reliability Scope, Goals, History of ARW Speakers: R. Giachino	05. Infrastructure Cryo, Electrical, Cooling Chair: D. Johnson	09. Maintenance for High Reliability Chair: P. Sampson	12. Medical Chair: S. Meyroneinc	16. Innovation Chair: L. Conradie	Optional Visit: Centre de Protontherapie d'Orsay Institut Curie
	10:30	Break	Break	Break	Break		
	11:00	02. Availability Tracking and Metrics Chair: G. Dodson	06. Accelerator Systems PS, RF, IonSource, Vacuum, etc Chair: V. Toma	10. Invited Speaker	13. Insuring Long Term Reliability Chair: D. Preddy	Workshop Highlights Summary / Closing Closing remarks LOC IOC Announcement of Next Workshop	
	12:30	Lunch	Lunch	Lunch	Lunch	End of Workshop	
	14:00	03. Reliability Before Design Chair: R. Giachino	07. Accelerator Control Hardware, Software, Interlocks, etc. Chair: D. Newhart	Visit of Synchrotron SOLEIL	14. Parallel Discussions Training/Teaching Use Case	Optional Visit: Palace of Versailles	
	15:30	Break	Break	Break	Break		
	16:00	04. Plenary Discussion Chair: D. Newhart	08 Failure Investigation Diagnostic, Post modum Root Cause, fault analysis Chair: K. Baggett	10. Poster Session Chair: M. Takao	15 Strategy for continuous operations Working toward a failure free machine Chair: L. Hardy		
	17:30	Meeting Sponsors		Return to Versailles (bus)	Meeting Sponsors		
	18:30	IOC Meeting			IOC Meeting		
18h-20h Welcome Reception and Registration			Gala 19:30-22:30		IOC Dinner		